




# How to Determine Revision A or B Intercom Hardware

**010935A Hardware Version  
(Firmware Version 0.01 up to Version 2.9.9)**



No Intrusion Detector Header  
010935A  
Firmware Version Label less than 3.0.0  
4 Post Header

**010935B Hardware Version  
(Firmware Version 3.0.0 and above)**



Intrusion Detector Header  
010935B or above  
Version 3.0.0 Firmware Label  
6 Post Header

## Loading Firmware on the VoIP Intercom that is PCB Board Specific

The most recent version of the VoIP Intercom (010935B) has some hardware changes that require a different firmware version that is not backward compatible with the earlier version of the intercom (010935A).

To ensure that you select the correct version of the firmware to download from [www.cyberdata.net](http://www.cyberdata.net) to go into your intercom, please use the information above to identify your hardware.

Firmware for the 010935B hardware will be identified as version 3.0.0 or above.

Firmware for the 010935A hardware will be identified as a version less than version 3.0.0 (such as V2.01, V2.02, and so on up to V2.99).